

2024



ANNUAL FIRE SAFETY REPORT

2024-2025 Academic Year



Campus Fire Safety Right-to-Know

The goal of the Clery Act is to ensure that students, prospective students, parents and employees have access to policy statements as well as fire statistics associated with each on-campus student housing facility, including the number of fires, cause of fires, injuries, deaths and property damage.

The information in this report presents information for facilities managed by UF Housing & Residence Life and on-campus student housing facilities owned or controlled by the University of Florida at separate campus locations for the calendar year 2023. Additionally, due to the novel coronavirus COVID-19, information on the temporary housing spaces used for quarantine purposes in calendar year 2021 is included in the 2024 Annual Fire Safety Report.

UNIVERSITY OF FLORIDA CAMPUS

The 2024 Annual Fire Safety Report includes the following UF campuses:

- Main Campus (Gainesville)
- UF Health Jacksonville
- Citrus Research and Education Center
- Everglades Research and Education Center
- Florida Medical Entomology Laboratory
- Fort Lauderdale Research and Education Center
- Gulf Coast Research and Education Center
- IFAS Equine Sciences Center
- IFAS Horse Teaching Unit
- Indian River Research and Education Center
- Mid Florida Research and Education Center
- North Florida Research and Education Center (Marianna)
- North Florida Research and Education Center (Quincy)
- Preservation Institute Nantucket
- Range Cattle Research and Education Center
- Southwest Florida Research and Education Center
- Tropical Aquaculture Laboratory
- Tropical Research and Education Center
- Vicenza Institute of Architecture
- West Florida Research and Education Center (Jay)
- Whitney Laboratory for Marine Bioscience

Definition of a Fire

Any instance of open flame or other burning in a place not intended to contain the burning or in an uncontrolled manner.

For inclusion of this report, the University of Florida will include all fires that meet defined guidance regardless of size, cause, or whether the fire results in injury, death, or property damage, including:

- Fires on the roof or the outside walls of a building even if the fire doesn't reach the inside;
- Incidents where there is evidence that there was burning;
- Fires in parking facilities and dining halls that are physically attached to and accessed directly from on-campus student housing authorities; and
- Fires reported to any official at the University of Florida

Classifications of a Fire

UNINTENTIONAL FIRE

A fire that does not involve an intentional human act to ignite or spread fire into an area where the fire should not be.

Causes are listed below:

- Cooking
- Smoking Materials
- Open flames
- Electrical
- Heating Equipment
- Hazardous products
- Machinery/Industrial
- Natural
- Other

INTENTIONAL FIRE

A fire that is ignited, or that results from a deliberate action, in circumstances where the person knows there should not be a fire.

UNDETERMINED FIRE

A fire in which the cause cannot be determined.

Table of Contents

3	Fire Safety Policies for the 2024-2025 Academic Year For the Gainesville, UF Health Jacksonville, and Separate Campuses
4	UF Gainesville Campus Fire Safety Information
7	UF Health Jacksonville Campus Fire Safety Information
9	Vicenza Institute of Architecture Fire Safety Information
11	UF Separate Campuses Fire Safety Information
13	Fire Statistics and Review of Fire Safety For the Gainesville, UF Health Jacksonville, and Separate Campuses
14	University of Florida Gainesville Campus Fire Statistics
15	Review of University of Florida Gainesville Fire Safety
20	Review of University of Florida Gainesville Fire Safety COVID-19 Temporary Housing Spaces used in calendar year 2021
21	UF Health Jacksonville Fire Statistics
22	UF Separate Campuses Fire Statistics

UF Compliance and Ethics

Clery Compliance

UNIVERSITY of FLORIDA



If you would like a copy of this report in an alternate format, please contact ADA Compliance at (352) 294-8720 or via email at adaservices@ufl.edu.

2024 Annual Security Report

The Annual Fire Safety Report is published separately from the Annual Security Report. The Annual Security Report can be directly accessed here: <https://clery.compliance.ufl.edu/annual-security-and-fire-safety-reports/>

You may also request a copy of the Annual Fire Safety Report or the Annual Security Report by emailing the Clery Act Compliance Program at clery@ufl.edu

Fire Safety Policies for the 2024-2025 Academic Year

For the Gainesville, UF Health Jacksonville, and Separate Campuses



From top left, clockwise: Broward Hall, Thomas Hall, Yulee Hall, Mallory Hall, and UF Whitney Laboratory for Marine Bioscience

UF Gainesville Campus

Fire Safety Information

HOW TO REPORT A FIRE

If a fire occurs in a residential facility on the Gainesville campus, students and employees should:

1. Call 9-1-1 for emergency response.
2. Call UF Housing and Residence Life at (352)392-2161 during business hours to report the fire. Fires can also be reported to any UF Housing & Residence Life staff member such as a Resident Assistant, Graduate Community Coordinator, or an Area Coordinator.

FIRE DRILLS

Staff conducts four mandatory fire drills annually, one during the first two weeks of each semester in each residence hall: Summer A/C, Summer B, Fall, and Spring. Staff may choose to conduct more than one fire drill at the beginning of the semester if additional training or education is needed for staff or residents. Residence Life supervisors provide prior notice of fire drills to UFPD and the Director of Housing for Facilities Management. Student staff are notified of the fire drills; prior notice is not made to residents. Staff completes written reports to the Director of Housing for Facilities Management after all fires, fire alarms, or fire drills.

GRADUATE AND FAMILY HOUSING AREAS:

Because Graduate/Family Housing apartments have direct outside access, no fire drills are required.

COMMUNITY STANDARDS

In some situations, a case may be handled by the Office of Student Conduct and Conflict Resolution within the Dean of Students Office. Please refer to the Student Honor Code and Student Conduct Code (UF Regulation 4.040) for more information including the student conduct process and student rights at <https://policy.ufl.edu/regulation/4-040/>. All Housing Community Standards including Fire Safety community standards is available online at https://housing.ufl.edu/wp-content/uploads/2024/08/2024-2025_HRL_CommunityStandards.pdf

2024-2025 SINGLE STUDENT COMMUNITY STANDARDS

U.18. FIRE SAFETY

A. EVACUATION - Immediate evacuation when an alarm sounds, and/or emergency flashing lights have been activated and/or when

instructed to do so by Housing and Residence Life staff or emergency personnel is mandatory. Re-entry into a building before receiving confirmation from Housing and Residence Life staff, UFPD, the fire department, or other emergency personnel is also prohibited. Re-entry is prohibited while the alarm is sounding and the strobe lights are flashing. For safety reasons, using an elevator to evacuate a building is also prohibited.

B. COOKING/APPLIANCE -

1. Residents and their guests must not leave appliances and their food items unattended while cooking with appliances at any time. Residents and their guests are responsible for the proper use of approved cooking appliances, use of residence hall/apartment ovens, attentiveness to food items while using the appliances. Residents will be held responsible for any damages that may occur.
2. Residents may not use toaster ovens, airstream ovens, electric frying pans, waffle irons, hot plates, deep fryers, rice cookers, and grills without flames in their room. These items may only be used in kitchen areas.
3. Residents may not have more than two microwave ovens in a room/apartment. microwaves cannot exceed 1500 watts.
4. Barbeque grills cannot be used less than 15 feet from a building. The use of grills is prohibited under any covered walkways, landings, or balconies. For infinity Hall residents, grills of any kind are not permitted in or outside of the facility.
5. Refrigerators cannot exceed 3.5 amps nor 12 cubic feet.

C. CANDLES AND AIR FRESHENERS -

1. Possession or use of all candles (including wickless and candle warmers), incense, oil diffusers, spray diffusers, wax warmers, or any sort of open-flamed device for any purpose is prohibited in the residence halls/apartments.
2. Plug-in type air fresheners and diffusers are prohibited.

D. EXTENSION CORDS/MULTI-PLUG ADAPTORS -

- For the protection of the residential community, residents are permitted to use extension cords with the following restrictions:
1. Only UL (Underwriters Laboratories) certified three-prong grounded extension cords that are 14 gauge or heavier are permitted to be possessed and/or used inside the residence halls.
 2. The extension cord must be equipped to plug in one item only. an extension cord that meets all other requirements and is designed for more than one item to be plugged into it

is prohibited because this type of extension cord is considered a multi-plug device without a circuit breaker.

NOTE : The lower the gauge number, the heavier/thicker the cord is. Cords cannot exceed 10 feet in length. Only one appliance/item may be plugged into an extension cord; only one extension cord may be used per double outlet.

3. Only UL (Underwriters Laboratories) or eTL certified multi-plug adapters (otherwise known as a surge protector/ powerstrip) with circuit breakers are permitted to be possessed and/or used inside the residence halls/apartments. mini-generators with circuit breakers that back-up devices or conserve power are prohibited.
4. Up to three appliances/items may be plugged into one multi-plug adapter (otherwise known as a surge protector/ power strip) per double outlet. The maximum wattage for a double outlet is 1,500 watts.
5. Extension cords and multi-plug adapters (otherwise known as a surge protector/ power strip) may not be connected. A built-in outlet/plug on products such as appliances is prohibited from use.

NOTE : Rules concerning extension cords and multi-plug adapters (otherwise known as a surge protector/power strip) are written in compliance with State Fire Codes and the engineering specifications of our various buildings.

E. PERSONAL CARE ELECTRICAL

DEVICES - Hair/blow dryers, curling irons, straightening irons, and other personal care electric devices must be plugged directly into the outlets.

F. AIR CONDITIONERS/HEATERS

- Residents are prohibited from installing air conditioners or ceiling fans in their rooms/apartments. Residents are prohibited from plugging AC units into any other outlet not designed specifically for the unit. Open coil space heaters are also prohibited. Other appliances/items are prohibited from being plugged into outlets designed specifically for AC use.

G. LAMPS -

1. All "floor style" halogen lamps are prohibited in residence halls/apartments. Halogen lamps specifically designed and marketed as desk lamps that have a bulb that is fully unexposed behind a solid glass casing that is unable to be tampered with and is at 50 watts or less are acceptable. Only UL (Underwriter's Laboratories) or eTL approved lamps can be used in the residence halls/apartments.
2. Lava lamps are not permitted in the

UF Gainesville Campus

Fire Safety Information continued

residence halls/ apartments.

H. FIRE SAFETY DEVICES - Residents are prohibited from removing, covering, hanging items from or otherwise tampering with fire safety devices which include but are not limited to smoke detectors, carbon monoxide detectors, fire alarms, horn strobes, fire extinguishers, sprinkler heads, and pipes that serve as a safety precaution to prevent fires, carbon monoxide, and other concerns.

U.04. SMOKING/TOBACCO

- A. Pursuant to UF - 2.022 of the University of Florida Regulations, tobacco use, either by smoking or other means, is prohibited in all areas of the University campus. policy.ufl.edu/regulation/2-022/.
- B. UF is a smoke-free, vape-free, and tobacco-free campus. Under the regulation, smoking, vaping, and use of tobacco products (including electronic cigarettes) are prohibited in all areas of UF's campuses.
- C. Smoking, Vaping, Tobacco, and all devices used for smoking (i.e. e-cigarettes, hookahs, pipes, etc.) are not permitted in any of the residence hall rooms, units and facilities, including courtyards, elevators, stairwells, balconies, lounges, patios, etc. Throwing cigarettes on the ground is considered littering. ashes, buds, and burn marks will be considered evidence of smoking in a unit.
- D. Residents and guests under 21 years of age are prohibited from possessing any tobacco product, nicotine product, or nicotine dispensing devices.

2024-2025 GRADUATE & FAMILY HOUSING COMMUNITY STANDARDS

U.35. FIRE SAFETY

A. EVACUATION - Immediate evacuation when an alarm sounds and emergency flashing lights have been activated, and/or when instructed to do so by Housing and Residence Life staff or emergency personnel is mandatory. Re-entry into a building before receiving confirmation from Housing and Residence Life, UFPD, the fire department, or other emergency personnel is prohibited. Re-entry is prohibited while the alarm is sounding.

B. COOKING - Residents and guests are prohibited from leaving food items unattended while cooking with appliances at any time. Residents and guests are responsible for the proper use of cooking appliances and attention to food items while using the appliances and will be held responsible for any damages that may occur.

C. STOVETOP/BACKSPASH &

RANGEHOODS Stovetop/backsplash and rangehoods must be free of flammable items such as cardboard, cloth, plastic wrap, aluminum foil, and newspapers. Burner trays, range hoods, counter-tops, and walls adjacent to the range are prohibited from being covered with any material.

D. AIR CONDITIONERS (CORY RESIDENTS ONLY) - Corry Village residents in non-renovated units may be able to supply their own air conditioners. Residents must secure approval from the Housing and Residence Life staff. Installation must be performed by Housing and Residence Life staff and there is a charge for installation.

E. HEATERS - Personal heaters, including but not limited to open coil space heaters, radiant heaters, or kerosene heaters are prohibited.

F. BARBECUE GRILLS - Persons are only permitted to use barbecue grills at a safe distance (15 feet or more) from all buildings. The use of grills is prohibited under any covered walkways, landings, or balconies. Grills must be attended by the resident while lit and in use, and/or still hot to touch. Propane grills are only allowed if the propane container is under 1.5 pounds. The container should be stored inside the apartment away from electrical appliances, direct sunlight, and heat sources. The storage of grills MUST be on the ground floor of the building. Ground floor residents may store a grill outside of their apartment. Second floor residents MUST store their grills on the ground floor in the designated storage area(s). **No grills are allowed to be stored or operated on the second floor of a residential apartment and/or village building.** See U.36 for storage of chemicals/charcoal policy.

G. LAMPS - all "floor style" halogen lamps are prohibited in graduate and Family Housing apartments. Halogen lamps specifically designed and marketed as desk lamps that have a bulb that is fully unexposed behind a solid glass casing that is unable to be tampered with and is at 50 watts or less are acceptable. Appropriate Village and/or maintenance staff shall decide if a halogen lamp meets qualifications. **Only UL (Underwriter's Laboratories) and ETL approved lamps can be used in the residence facilities.**

H. CANDLES AND AIR FRESHENERS -

1. Candles and incense must be supervised by residents. Residents are required to be present in the room in which candles and incense are in use.
2. For environmental safety reasons, oil diffusers and spray diffusers, are prohibited in the apartments. Plug-in type air fresheners and diffusers are prohibited.

I. FIRE SAFETY DEVICES - Residents are prohibited from removing, covering, hanging

items from or otherwise tampering with fire safety devices which include but are not limited to smoke detectors, carbon monoxide detectors, fire alarms, horn strobes, fire extinguishers, sprinkler heads, and pipes that serve as a safety precaution to prevent fires, carbon monoxide, and other concerns.

J. PERSONAL CARE ELECTRICAL DEVICES - Hair/blow dryers, curling irons, straightening irons, and other personal care electric devices must be plugged directly into the outlets.

U.47. SMOKING/TOBACCO

- A. Pursuant to UF Regulation 2.022 of the University of Florida Regulations, tobacco use, either by smoking or other means, is prohibited in all areas of the University campus. To view the entire policy, please visit policy.ufl.edu/regulation/2-022/.
- B. UF is a smoke-free, vape-free, and tobacco-free campus. Under the Regulation, smoking, vaping, and use of tobacco products (including electronic cigarettes) are prohibited in all areas of UF's campuses.
- C. Smoking, Vaping, Tobacco, and all devices used for smoking (i.e. e-cigarettes, hookahs, pipes, etc.) are not permitted in any of the residence hall rooms, units and facilities, including courtyards, elevators, stairwells, balconies, lounges, patios, etc. Throwing cigarettes on the ground is considered littering. ashes, buds, and burn marks will be considered evidence of smoking in a unit.
- D. Residents and guests under 21 years of age are prohibited from possessing any tobacco product, nicotine product, or nicotine dispensing devices.

2024-2025 THE CONTINUUM COMMUNITY STANDARDS

U.61. FIRE SAFETY

A. EVACUATION - Residents must evacuate immediately when an alarm sounds, and/or emergency flashing lights have been activated, and/or when instructed to do so by Housing and Residence Life/Continuum apartments staff or emergency personnel. Re-entry into a building before receiving confirmation from Housing and Residence Life/Continuum apartments staff, police officers, the fire department, or other emergency personnel is prohibited. Re-entry is prohibited while the alarm is sounding.

B. COOKING - Residents and guests must not leave food items unattended while cooking with appliances at anytime. Residents and guests are responsible for the proper use of approved

UF Gainesville Campus

Fire Safety Information continued

cooking appliances and attention to food items while using the appliances. Residents will be held responsible for any damages that may occur.

C. STOVETOP/BACKSPLASH & RANGEHOODS Stovetop/backsplash and rangehoods must be free of flammable items such as cardboard, cloth, plastic wrap, aluminum foil, and newspapers. Burner trays range hoods, counter tops and walls adjacent to the range are prohibited from being covered with any material.

D. HEATERS - Personal heaters, including but not limited to open coil space heaters, radiant heaters, or kerosene heaters are prohibited.

E. BARBECUE GRILLS - Grills of any kind inside or outside of the apartment unit are prohibited.

F. LAMPS - All halogen lamps are prohibited in apartments.

G. CANDLES AND INCENSE - Residents cannot leave lit candles or incense unattended.

H. FIRE SAFETY DEVICES - Residents are prohibited from removing, covering, hanging items from or otherwise tampering with fire safety devices which include but are not limited to smoke detectors, carbon monoxide detectors, fire alarms, horn strobes, fire extinguishers, sprinkler heads, and pipes.

I. HOLIDAY DECORATIONS

1. Stickers, glow in the dark stars, sticky tack, and other adhesives are prohibited.
2. Signs and banners may not be hung from patios, balconies, windows or any other area that would be visible from the exterior without prior approval from Continuum apartments.

J. PERSONAL CARE ELECTRICAL

DEVICES - Hair/blow dryers, curling irons, straightening irons, and other personal care electric devices must be plugged directly into the outlets.

U.83. SMOKING/TOBACCO

The Continuum is a tobacco-free facility. Smoking and the use of tobacco products are prohibited inside the buildings, common hallways, individual apartments, and within the pool areas.

FIRE PREVENTION

The best fire protection is prevention and is the result of the combined efforts of student, staff and professional inspecting personnel.

Students and staff should be made aware of the most common causes of fires which are frequently overlooked or ignored, and which in many cases have resulted in the loss of life and property. The following are common causes of fires that have occurred or could occur in residence facilities:

- Intentional ignition of accumulated trash.
- Attempt to "smoke" a friend out of his room.
- Use of inflammable liquids as cleaning agents.

- Storage of inflammable liquids within a living area.
- Overloading electrical circuits.
- Extension cords which are suspended on nails or placed in a manner that causes wear of the protective covering increases the possibility of short circuits.
- Leaving appliances plugged in and unattended.
- Poor housekeeping (accumulation of trash, newspapers, magazines, etc.).
- Operation of ventilating fan near drapes or curtains which may be drawn into the blades, stopping the machine, thus causing the motor to heat up and ignite the material.
- Drying clothing on heating devices.

Resident Training/Education Written Materials Undergraduate Residence Halls

- Community Standards link provided during online contract process, during Preview, and at time of check-in.
- The Department of Housing and Residence Life presentation and handouts during freshmen orientation includes fire safety information.
- All residence halls have posted fire safety educational materials.

Resident Training/Education Experiential Undergraduate Residence Halls

- Fire drills at the beginning of each semester.
- Fire safety inspections at the beginning of each semester.
- Fire safety seminar sanction for residents found in violation of fire safety community standards.

Resident Training/Education Written Materials Graduate and Family Housing Web Site

The safety of the Village is the responsibility of each resident. Residents are asked to review the Housing Community Standards on the website for specific information on what items are allowed in their apartments highlighting these areas:

- Do not tamper with fire alarms, fire extinguishers or other.
- Do not cover or disconnect the apartment smoke detectors.
- Do not hang items on sprinkler heads.
- Leaving food on the stove unattended is one of the main causes of fires.
- Keep breezeways and stairwells clear. Do not lock or store bicycles in stairwells.

The Resident Guide as well as The Villager is also part of the rental agreement because new policies, procedures, and other official information are published there. Thus, the importance of reading every issue of The Villager is stressed.

Posted periodically in Weekly Community Update, weekly email sent to all GFH residents:

Smoke Detectors

Smoke detectors should not be unhooked or covered as this is a fire code violation. Please make sure your smoke detectors are in working order. If


not, complete an iService request or Maintenance Work Request.

New Resident Floor Meeting

Every new resident attends a new resident floor meeting upon moving in. At this meeting, fire safety procedures are reviewed, which include smoking in the area; safe grilling practices; how to sound the building fire alarm system; and apartment evacuation when the building alarm is sounding. Additionally, residents are encouraged to develop a family fire escape plan. This is an individual responsibility of the residents.

UF GAINESVILLE FACILITY UPGRADE

A Housing Master Plan exists that includes the installation of sprinklers in residence facilities; however, the funding cannot be "secured" more than one year prior to the proposed project. The funding source for these projects is student rent which is approved on an annual basis by the Board of Trustees. If additional funding sources become available for sprinkler projects, master plan target dates could be moved forward to provide sprinkler systems for Simpson Hall and Graham Hall.



UF Health Jacksonville Campus

Fire Safety Information

HOW TO REPORT A FIRE

If a fire occurs in a residential facility on the Jacksonville campus, students and employees should:

1. Call (904) 244-2222. Operators will notify Fire Department, as well as, dispatching on-site responders.

UF HEALTH JACKSONVILLE ON-CAMPUS HOUSING AREA

Staff conducts at least one fire drill per year. Staff may choose to conduct additional fire drills if more training or education is needed for staff or residents. Fire drills are coordinated by the UF Health Jacksonville Safety Department in cooperation with the College of Medicine, Office of Student Affairs. The UF Health Jacksonville Safety Department provides prior notice of drills to the security department. Prior notice may or may not be made to residents. The Jacksonville Safety Department conducts all aspects of the drill and is available to assist students during the drill. The UF Health Jacksonville Safety Department completes a written report after all fires, fire alarms, or fire drills.

Upon check-in to the dorm, all residents are provided information about the location of fire extinguishers within the dorm, the procedure to follow when smoke/fire is discovered and where to report outside of the dorm when a fire alarm sounds. Additionally, this information is posted throughout the dorm for student review. In the event that smoke/fire is discovered within the dorm, students are instructed to:

- R – rescue those in danger
- A – pull alarm & call 4-2222 (campus phones) or (904) 244-2222 (non-campus phones)
- C – contain the fire
- E – extinguish and/or evacuate

If a student uses a fire extinguisher, he/she is instructed to:

- P – pull the pin
- A – aim at the base of the fire
- S – squeeze the handle
- S – sweep from side to side

RESIDENCY

There is no residency requirement at the UF HSC-J. Students voluntarily become part of the campus residential community. By accepting dorm keys, they acknowledge and agree to follow the standards of the community. Please refer to the Student Honor Code and Student Conduct Code (UF Regulation 4.040) for more information including the student conduct process and student rights at <https://policy.ufl.edu/regulation/4-040/>.

COMMUNITY STANDARDS FIRE SAFETY

A. EVACUATION - Immediate evacuation when an alarm sounds, and/or emergency flashing lights have been activated, and/or when instructed to do so by appropriate hall staff is mandatory. Re-entry into a building before receiving confirmation from appropriate Safety/Security personnel, the fire department, or other emergency personnel is prohibited. Re-entry is not permitted while the alarm is sounding. For safety reasons, using an elevator to evacuate a building is not permitted. Please use stairwells.

B. COOKING - Persons should not leave their food items unattended on the stove or in the oven at any time. Persons are responsible for the proper use of approved cooking appliances and attention to food items while using the appliances and will be responsible for any damages that may occur.

C. COOKING APPLIANCES - Persons are allowed to use the following items in their room or kitchen areas: electric fondue pots, air stream ovens, electric crock pots, coffee pots, hotdog cookers, drip coffee makers, bread makers and popcorn poppers. These items are permitted so long as they are single units with sealed heating elements. Convenience items such as blenders, mixers, can openers and juicers are also permitted.

The following items are permitted, but may be used only in kitchen areas: toasters, toaster ovens, frying pans, electric hamburger cookers, waffle irons, ceramic sealed hot plates, hot plates with exposed coils, deep fryers, and counter-top electric grills without flames (e.g. "George Foreman™" grills).

D. MICROWAVE OVENS - Microwaves will be permitted in resident rooms provided the following guidelines are met: a) a maximum of two microwave ovens are permitted in a student room if each individual unit is 0.75 cubic feet or less; b) microwave ovens must be UL approved; c) each unit and/ or units combined must not exceed 1500 watts (only one microwave oven is permitted if the unit(s) exceeds 0.75 cubic feet and/or 1500 watts).

E. CANDLES AND INCENSE - Possession or use of all candles and incense for any purpose is prohibited in the residence halls.

F. EXTENSION CORDS/MULTI-PLUG ADAPTORS - For the protection of the residential community, residents are permitted to use extension cords with the following restrictions:

1. Only UL (Underwriters Laboratories) certified three-prong grounded extension cords that are 14 gauge or heavier are permitted to be

possessed and/or used inside the residence halls.

2. The extension cord must be equipped to plug in one item only. An extension cord that meets all other requirements and is designed for more than one item to be plugged into it is not allowed because this type of extension cord is considered a multi-plug device without a circuit breaker.

NOTE: The lower the gauge number, the heavier/thicker the cord is. Cords cannot exceed 10 feet in length. Only one appliance/item may be plugged into an extension cord; only one extension cord may be used per double outlet.

3. Only UL (Underwriters Laboratories) certified multi-plug adapters with circuit breakers are permitted to be possessed and/or used inside the residence halls. Mini-generators with circuit breakers that back-up devices or conserve power are prohibited.
4. Up to three appliances/items may be plugged into one multi-plug adapter per double outlet. The maximum wattage for a double outlet is 1500 watts.
5. Extension cords and multi-plug adapters may not be connected. Items may not be plugged into outlets/plugs contained in other items.
6. Air-freshener plug-ins (e.g. Glade™ plug-ins) with a built-in "outlet" may be used only if the outlet in the air-freshener is not used. NOTE: Regulations concerning extension cords and multi-plug adapters are written in compliance with State Fire Codes and the engineering specifications of our various buildings.

G. AIR CONDITIONERS/HEATERS - Residents may not install air conditioners or ceiling fans in their rooms. Residents may not plug AC units into any other outlet not designed specifically for the unit. Open coil space heaters are not permitted. Other appliances/items may not be plugged into outlets designed specifically for AC use.

H. RESIDENCE HALL DECORATIONS

1. "Live cut" trees (such as Christmas Trees) are prohibited in the residence halls.
2. Strands of lights (Holiday Lights) may be used in residence hallrooms but may not be plugged into each other to create a string of lights.
3. External doors, doorframes and hallways may not be decorated. Only one door nametag and message board is permitted per resident.
4. No flags, banners or other cloth/flammable decorations are to be hung on and/or from the ceiling. All decorations should be adhered to the decorative strip provided for posting or if none is provided, decorations should not be higher on the wall than the door frame.

UF Health Jacksonville Campus

Fire Safety Information continued

I. REFRIGERATORS - Are permitted in resident rooms provided the following guidelines are met:

- All refrigerators must be UL approved.
- Door gaskets must be in good condition.
- All refrigerators must be equipped with a (3) three prong grounded plug which must be plugged into the wall outlet.

NOTE: In cases in which the wall outlet is inaccessible, the refrigerator may be plugged into an extension cord that is ten feet in length or less, 14 gauge or thicker/heavier, and has room for only one item.

- Unit amperage must not exceed 3.5 amps.
- Unit size must not exceed 12 cubic feet.
- Students must maintain refrigerators in a safe and sanitary condition.

J. BARBECUE GRILLS - Grills are available for use and are located in the Picnic area by the North Garage. Contact on-site facilities.

K. LAMPS - All "floor style" halogen lamps are prohibited in residence halls. Halogen lamps specifically designed and marketed as desk lamps that have a bulb that is fully unexposed behind a solid glass casing that is unable to be tampered with and is at 50 watts or less are acceptable. Only UL (Underwriter's Laboratories) approved lamps can be used in the residence halls.

L. PERSONAL CARE ELECTRICAL DEVICES - Hair/blow dryers, curling irons, straightening irons, and other personal care electric devices must be plugged directly into the outlets.

M. SPRINKLERS - Residents are not permitted to hang items from, cover, or otherwise tamper with fire sprinkler devices. Must keep 18" clearance from the bottom of the sprinkler head throughout dorm room/ hallways/ etc.

SMOKING - The University of Florida has a "No Tobacco Policy." Smoking and tobacco use are prohibited in all facilities and areas of the University of Florida campus with no exception. This includes but is not limited to indoor and outdoor areas and properties. This policy applies to all faculty, staff, students, consultants, contractors, and visitors.

Fire Evacuation Procedures

1. When a fire alarm sounds, all residents are to leave the building immediately. Elevators are not to be used during the evacuation. Residents are to report to the student parking lot near the dorm.
2. Residents may re-enter the building only once they have been instructed to do so by the UF Health Jacksonville Safety Department, Director of Engineering or the Fire Chief.
3. During a fire/alarm/evacuation, The UF

Health Jacksonville Safety Department will conduct the initial communication between Jacksonville Security, the Fire Department, students, and the Dean(s) of students.

4. At the close of Fire/Alarm/Drill, the UF Health Jacksonville Safety Department will complete a Fire/Alarm/Drill Report.

STAFF TRAINING/EDUCATION WRITTEN MATERIALS

Staff in the College of Medicine's Office of Educational Affairs are familiar with the policies and procedures for fire safety on the UF Health Jacksonville Campus. These policies and procedures include, but are not limited to, evacuation plans, fire extinguisher instructions, and devices that are allowed/not allowed in the dorm. Appropriate staff have read, reviewed and acknowledged their receipt of these policies and procedures.

FIRE PREVENTION

The best fire protection is prevention and is the result of the combined efforts of student, staff and professional inspection personnel.

Students, staff, and faculty should be made aware of the most common causes of fires which are frequently overlooked or ignored, and which in many cases have resulted in the loss of life and property. The following are common causes of fires that have occurred or could occur in residence facilities:

- Intentional ignition of accumulated trash.
- Attempt to "smoke" a friend out of his room.
- Use of inflammable liquids as cleaning agents.
- Storage of inflammable liquids within a living area.
- Overloading electrical circuits.
- Extension cords which are suspended on nails or placed in a manner that causes wear of the protective covering increases the possibility of short circuits.
- Leaving appliances plugged in and unattended.
- Poor housekeeping (accumulation of trash, newspapers, magazines, etc.).
- Operation of ventilating fan near drapes or curtains which may be drawn into the blades, stopping the machine, thus causing the motor to heat up and ignite the material.
- Drying clothing on heating devices.

Residents are also asked to remember these considerations:

- Do not tamper with fire alarms, fire extinguishers or other fire equipment.
- Ensure fire extinguishers are free from obstruction.
- Do not cover or disconnect the dorm smoke detectors.

- Do not hang items on sprinkler heads.
- Leaving food on the stove unattended is one of the main causes of fires.
- Keep breezeways and stairwells clear. Do not lock or store bicycles in stairwells.
- Smoke detectors should not be unhooked or covered as this is a fire code violation. Please make sure your smoke detectors are in working order. If not, contact Jacksonville Facility Control Room at (904)244-2232. Plans for future improvements in fire safety, if determined necessary by the institution.

UF HEALTH JACKSONVILLE FACILITY UPGRADE

Ongoing upgrades to fire alarm systems including the installation/upgrade of fire sprinklers, heat detectors, smoke detectors, etc. are routinely budgeted for as part of the department Master Plan for facilities.

WHO TO CONTACT

For any safety/ security related questions or concerns, both the Safety and Security offices are located on the 1st floor directly below the dorms.

UF Health Jacksonville Safety
(904) 244-4361

UF Health Jacksonville Security Department
(904) 244-4211



Vicenza Institute of Architecture

Fire Safety Information

HOW TO REPORT A FIRE

If a fire occurs in a residential facility at the Vicenza Institute of Architecture, students and employees should follow these instructions that are provided during orientation:

Should you notice a fire, you must notify the VIA monitors (who knows about the fire extinguishers and how to use it) and the monitors will intervene immediately and declare the pre-alarm.

This consist in:

- Notify immediately the coordinator (Franca Stocco tel. +39 348 30 3014) who will come to VIA;
- Turning off the electricity. Each room, except the studio, has an electric panel;
- To open the control panel at the far end of the studio room, break the seals of the red glass box located nearby the big electric control panel. Take the keys of the control panel door and turn off the main switch: GENERALE;
- If the fire is large, the Fire Department (Vigili del Fuoco) must be called (Tel 115) and if necessary also the First Aid (Pronto Soccorso - Tel 118 or 113);
- Give the signal of evacuation. There is a "stadium horn" inside the red box nearby the fire extinguisher located next to the VIA main door;
- Coordinate the operations.

If the fire is extinguished in 5-10 minutes the coordinator can declare the alarm to be over.

This consists in:

- Notify everyone that the emergency is over;
- Check that there are not hotbed or embers anywhere;
- Ventilate the space to eliminate gas and vapours;
- Before people are allowed into the space again an expert should check that there is no damage to the structure, no damage to the electrical system and to the machinery. Finally ask the Fire Department (Vigili del Fuoco) to check the space;
- If necessary, notify the electric company (AIM).

VICENZA INSTITUTE OF ARCHITECTURE HOUSING AREAS

Staff conducts at least two fire drills per year.

Fire Drills are coordinated by the on-site coordinator and management firm at the Vicenza Institute of Architecture campus. Prior notice may or may not be made to residents.

Staff and the management firm conducts all aspects of the drill and are available to assist students during the drill. Staff and the management firm complete a written report after all fires, fire alarms, or fire drills.

In the event that smoke/fire is discovered within the VIA studio, students are instructed to:

- R - rescue those in danger
- A - pull alarm & call 9-1-1
- C - contain the fire
- E - extinguish and/or evacuate

If a student uses a fire extinguisher, he/she is instructed to:

- P - pull the pin
- A - aim at the base of the fire
- S - squeeze the handle
- S - sweep from side to side

RESIDENCY

Students voluntarily become part of the campus residential community. By accepting apartment keys, they acknowledge and agree to follow the standards of the community. This information is provided during orientation. Please refer to the Student Honor Code and Student Conduct Code (UF Regulation 4.040) for more information including the student conduct process and student rights at <https://policy.ufl.edu/regulation/4-040/>.

FIRE SAFETY

COOKING - Persons should not leave their food items unattended on the stove or in the oven at any time. Persons are responsible for the proper use of approved cooking appliances and attention to food items while using the appliances and will be responsible for any damages that may occur.

COOKING APPLIANCES - Persons are NOT allowed to use the following items in their rooms: electric fondue pots, air stream ovens, electric crock pots, coffee pots, hotdog cookers, frying pans, drip coffee makers, toasters (not toaster ovens), bread makers and popcorn poppers. Convenience items such as blenders, mixers, can openers and juicers are also permitted.

The following items are permitted, but may be used only in kitchen areas: toaster ovens, electric hamburger cookers, waffle irons, ceramic sealed hot plates, hot plates with exposed coils, deep fryers, and counter-top electric grills without flames (e.g. "George Foreman™" grills).

MICROWAVE OVENS - Microwaves will be permitted in resident kitchens and studio kitchenette.

CANDLES AND INCENSE - Possession or

use of all candles and incense for any purpose is prohibited in the residence halls.

EXTENSION CORDS/MULTI-PLUG ADAPTORS - For the protection of the residential community, residents are permitted to use extension cords with the following restrictions:

1. EU compliance certified three-prong grounded extension cords are permitted to be possessed and/or used inside the residence halls and studio.
2. The extension cord must be equipped to plug in one item only. An extension cord that meets all other requirements and is designed for more than one item to be plugged into it is not allowed because this type of extension cord is considered a multi-plug device without a circuit breaker.

NOTE: The lower the gauge number, the heavier/thicker the cord is. Cords cannot exceed 10 feet in length. Only one appliance/item may be plugged into an extension cord; only one extension cord may be used per double outlet.

3. Only EU compliance certified multi-plug adapters with circuit breakers are permitted to be possessed and/or used inside the residence halls. Mini-generators with circuit breakers that back-up devices or conserve power are prohibited.
4. Up to three appliances/items may be plugged into one multi-plug adapter per double outlet. The maximum wattage for a double outlet is 1500 watts.
5. Extension cords and multi-plug adapters may not be connected. Items may not be plugged into outlets/plugs contained in other items.

AIR CONDITIONERS/HEATERS

Most of the Vicenza Institute of Architecture facilities do not have AC. Heaters are periodically controlled, thermostats are controlled remotely by the school and students cannot adjust them.

RESIDENCE HALL DECORATIONS - Decorations are prohibited.

REFRIGERATORS/ELECTRICAL

DEVICES - These devices are permitted in apartments provided that they are EU approved. Students and faculty are provided information upon check-in regarding electricity usage in Italy, including kilowattage limits and directions on device usage for the studio and apartments.

BARBECUE GRILLS - Barbecue grills are prohibited.

LAMPS - Lamps are supplied by the Vicenza Institute of Architecture.

SPRINKLERS - Italian fire code requires special permissions for the use of sprinklers, and in residential buildings, they most often cannot

Vicenza Institute of Architecture

Fire Safety Information continued

be installed.

SMOKING – Smoking is prohibited in all facilities.

FIRE EVACUATION PROCEDURES

- Stop any activity.
- Leave your personal objects where they are.
- Stay calm, do not push, do not run or scream.
- Exit neatly following the line leader. Usually VIA monitors have the responsibility of being line leaders.
- Proceed in a single file line holding hands or with your hand on the shoulder of the person in front of you.
- Respect the priorities depending on the seriousness of the evacuation.
- Follow the emergency exit signs indicated along the stair case.
- Go to the meeting point established outside the courtyard in the street, Contrà Ss. Apostoli 51, and from there leave VIA.

IN CASE OF EVACUATION DUE TO FIRE PLEASE REMEMBER:

- In case of smoke along the exit ways, walk crouched down and breathe through a handkerchief (preferably wet).
- If you cannot go through the corridors or the exit ways or if they are filled with smoke, do not leave the room where you are in instead seal the cracks of the doors, possibly with wet clothes; go to the window and call for help.
- If you are blocked inside the main studio and you cannot go through the staircase filled with smoke, close the studio door, go to the far end of the class room, nearby the small electric panel there is a red container. Break the seal, take the key and open the door position 1 meter higher. This exit will lead you to a staircase of a private condominium which will eventually take you to the street Contrà Ss. Apostoli 51.

STAFF TRAINING/EDUCATION WRITTEN MATERIALS

Staff at the Vicenza Institute of Architecture are familiar with the policies and procedures for fire safety at that particular campus. These policies and procedures include, but are not limited to, evacuation plans, fire extinguisher instructions, and devices that are allowed/not allowed in the dorm. Appropriate staff have read, reviewed and acknowledged their receipt of these policies and procedures.

FIRE PREVENTION

The best fire protection is prevention and is the result of the combined efforts of student, staff and professional inspecting personnel.



Students, staff, and faculty should be made aware of the most common causes of fires which are frequently overlooked or ignored, and which in many cases have resulted in the loss of life and property. The following are common causes of fires that have occurred or could occur in residence facilities:

- Intentional ignition of accumulated trash.
- Attempt to “smoke” a friend out of his room.
- Use of inflammable liquids as cleaning agents.
- Storage of inflammable liquids within a living area.
- Overloading electrical circuits.
- Extension cords which are suspended on nails or placed in a manner that causes wear of the protective covering increases the possibility of short circuits.
- Leaving appliances plugged in and unattended.
- Poor housekeeping (accumulation of trash, newspapers, magazines, etc.).
- Operation of ventilating fan near drapes or curtains which may be drawn into the blades, stopping the machine, thus causing the motor to heat up and ignite the material.
- Drying clothing on heating devices.

Residents are also asked to remember these considerations:

- Do not tamper with fire alarms, fire extinguishers or other.

- Do not hang items on sprinkler heads.
- Leaving food on the stove unattended is one of the main causes of fires.
- Keep breezeways and stairwells clear. Do not lock or store bicycles in stairwells.
- Smoke detectors should not be unhooked or covered as this is a fire code violation. Please make sure your smoke detectors are in working order. If not, contact Whitney Laboratory Facilities. Plans for future improvements in fire safety, if determined necessary by the institution.

VICENZA INSTITUTE OF ARCHITECTURE FACILITY UPGRADES

There are no planned upgrades at this time.

UF Separate Campuses

Fire Safety Information

HOW TO REPORT A FIRE

If a fire occurs in a residential facility at one of UF's separate campuses, students and employees should:

1. Call 9-1-1 for emergency response.
2. Call UF Environmental Health & Safety at (352)392-159 to report the fire.

UF SEPARATE CAMPUSES ON-CAMPUS HOUSING AREAS

Staff conducts at least one fire drill per year. Staff may choose to conduct additional fire drills if more training or education is needed for staff or residents. **Fire Drills are coordinated by the Operations Department at each Separate Campus location. Prior notice may or may not be made to residents. Operations/facilities staff conducts all aspects of the drill and are available to assist students during the drill. All Operations/Facilities departments complete a written report after all fires, fire alarms, or fire drills.**

Upon check-in to an On-Campus Student Housing Facility, all residents should identify the location of fire extinguishers within the dorm (if available), the procedure to follow when smoke/fire is discovered and where to report outside of the dorm when a fire alarm sounds. Additionally, this information is posted throughout the dorm for student review near exits. In the event that smoke/fire is discovered within the dorm, students are instructed to:

- R – rescue those in danger
- A – pull alarm & call 9-1-1
- C – contain the fire
- E – extinguish and/or evacuate

If a student uses a fire extinguisher, he/she is instructed to:

- P – pull the pin
- A – aim at the base of the fire
- S – squeeze the handle
- S – sweep from side to side

RESIDENCY

Students voluntarily become part of the campus residential community. By accepting dorm keys, they acknowledge and agree to follow the standards of the community. Please refer to the Student Honor Code and Student Conduct Code (UF Regulation 4.040) for more information including the student conduct process and student rights at <https://policy.ufl.edu/regulation/4-040/>.

COMMUNITY STANDARDS FIRE SAFETY

A. EVACUATION - Immediate evacuation when an alarm sounds, and/or emergency flashing lights have been activated, and/or when instructed to do so by appropriate hall staff is mandatory. Re-entry into a building before receiving confirmation from appropriate hall staff, UFPD, the fire department, or other emergency personnel is prohibited. Re-entry is not permitted while the alarm is sounding. For safety reasons, using an elevator to evacuate a building is not permitted.

B. COOKING - Persons should not leave their food items unattended on the stove or in the oven at any time. Persons are responsible for the proper use of approved cooking appliances and attention to food items while using the appliances and will be responsible for any damages that may occur.

C. COOKING APPLIANCES - Persons are NOT allowed to use the following items in their rooms: electric fondue pots, air stream ovens, electric crock pots, coffee pots, hotdog cookers, frying pans, drip coffee makers, toasters (not toaster ovens), bread makers and popcorn poppers. Convenience items such as blenders, mixers, can openers and juicers are also permitted.

The following items are permitted, but may be used only in kitchen areas: toaster ovens, electric hamburger cookers, waffle irons, ceramic sealed hot plates, hot plates with exposed coils, deep fryers, and counter-top electric grills without flames (e.g. "George Foreman™" grills).

D. MICROWAVE OVENS - Microwaves will be permitted in resident rooms provided the following guidelines are met: a) a maximum of two microwave ovens are permitted in a student room if each individual unit is 0.75 cubic feet or less; b) microwave ovens must be UL approved; c) each unit and/ or units combined must not exceed 1500 watts (only one microwave oven is permitted if the unit(s) exceeds 0.75 cubic feet and/or 1500 watts).

E. CANDLES AND INCENSE -

Possession or use of all candles and incense for any purpose is prohibited in the residence halls.

F. EXTENSION CORDS/MULTI-PLUG ADAPTORS -

For the protection of the residential community, residents are permitted to use extension cords with the following restrictions:

1. Only UL (Underwriters Laboratories) certified three-prong grounded extension cords that are 14 gauge or heavier are permitted to be possessed and/or used inside the residence

halls.

2. The extension cord must be equipped to plug in one item only. An extension cord that meets all other requirements and is designed for more than one item to be plugged into it is not allowed because this type of extension cord is considered a multi-plug device without a circuit breaker.

NOTE: The lower the gauge number, the heavier/thicker the cord is. Cords cannot exceed 10 feet in length. Only one appliance/item may be plugged into an extension cord; only one extension cord may be used per double outlet.

3. Only UL (Underwriters Laboratories) certified multi-plug adapters with circuit breakers are permitted to be possessed and/or used inside the residence halls. Mini-generators with circuit breakers that back-up devices or conserve power are prohibited.

4. Up to three appliances/items may be plugged into one multi-plug adapter per double outlet. The maximum wattage for a double outlet is 1500 watts.

5. Extension cords and multi-plug adapters may not be connected. Items may not be plugged into outlets/plugs contained in other items.

6. Air-freshener plug-ins (e.g. Glade™ plug-ins) with a built-in "outlet" may be used only if the outlet in the air-freshener is not used. NOTE: Regulations concerning extension cords and multi-plug adapters are written in compliance with State Fire Codes and the engineering specifications of our various buildings.

G. AIR CONDITIONERS/HEATERS -

Residents may not install air conditioners or ceiling fans in their rooms. Residents may not plug AC units into any other outlet not designed specifically for the unit. Open coil space heaters are not permitted. Other appliances/items may not be plugged into outlets designed specifically for AC use. NOTE: Thomas and Buckman residents please speak with hall staff concerning AC use in your area and follow applicable guidelines for Thomas and Buckman Halls.

H. RESIDENCE HALL DECORATIONS

1. "Live cut" trees (such as Christmas Trees) are prohibited in the residence halls.
2. Strands of lights (Holiday Lights) may be used in residence hallrooms but may not be plugged into each other to create a string of lights.
3. External doors, doorframes and hallways may not be decorated. Only one door nametag and message board is permitted per resident.
4. No flags, banners or other cloth/flammable decorations are to be hung on and/or from the ceiling. All decorations should be adhered

UF Separate Campuses

Fire Safety Information continued

to the decorative strip provided for posting or if none is provided, decorations should not be higher on the wall than the door frame.

I. REFRIGERATORS - Are permitted in resident rooms provided the following guidelines are met:

- All refrigerators must be UL approved.
- Door gaskets must be in good condition.
- All refrigerators must be equipped with a (3) three prong grounded plug which must be plugged into the wall outlet.

NOTE: In cases in which the wall outlet is inaccessible, the refrigerator may be plugged into an extension cord that is ten feet in length or less, 14 gauge or thicker/heavier, and has room for only one item.

- Unit amperage must not exceed 3.5 amps.
- Unit size must not exceed 12 cubic feet.
- Students must maintain refrigerators in a safe and sanitary condition.

J. BARBECUE GRILLS - Persons are permitted to use barbecue grills at a safe distance (50 feet or more) from all buildings. The use of grills is not permitted under any covered walkways, landings, or balconies. Residents are responsible for attentive supervision in proper use of all grills while cooking. Propane tanks should not be stored in or within 50 feet of buildings.

K. LAMPS - All "floor style" halogen lamps are prohibited in residence halls. Halogen lamps specifically designed and marketed as desk lamps that have a bulb that is fully unexposed behind a solid glass casing that is unable to be tampered with and is at 50 watts or less are acceptable. Only UL (Underwriter's Laboratories) approved lamps can be used in the residence halls.

L. PERSONAL CARE ELECTRICAL DEVICES - Hair/blow dryers, curling irons, straightening irons, and other personal care electric devices must be plugged directly into the outlets.

M. SPRINKLERS - Residents are not permitted to hang items from, cover, or otherwise tamper with fire sprinkler devices.

SMOKING - The University of Florida has a "No Tobacco Policy." Smoking and tobacco use are prohibited in all facilities and areas of the University of Florida campus with no exception. This includes but is not limited to indoor and outdoor areas and properties. This policy applies to all faculty, staff, students, consultants, contractors, and visitors.

Fire Evacuation Procedures

1. When a fire alarm sounds, all residents are to leave the building immediately. Elevators are not to be used during the evacuation. Residents are to report to the student parking



lot near the dorm.

2. Residents may re-enter the building only once they have been instructed to do so by the applicable Separate Campus Facilities Department.
3. At the close of Fire/Alarm/Drill, the applicable Separate Campus Facilities Department will complete a Fire/Alarm/Drill Report. This form must be completed and turned into the applicable Separate Campus Facilities Department (within 24 hours of the Drill or Alarm) for records retention purposes.

STAFF TRAINING/EDUCATION WRITTEN MATERIALS

Staff at each Separate Campus are familiar with the policies and procedures for fire safety at that particular campus. These policies and procedures include, but are not limited to, evacuation plans, fire extinguisher instructions, and devices that are allowed/not allowed in the dorm. Appropriate staff have read, reviewed and acknowledged their receipt of these policies and procedures.

FIRE PREVENTION

The best fire protection is prevention and is the result of the combined efforts of student, staff and professional inspecting personnel.

Students, staff, and faculty should be made aware of the most common causes of fires which are frequently overlooked or ignored, and which in many cases have resulted in the loss of life and property. The following are common causes of fires that have occurred or could occur in residence facilities:

- Intentional ignition of accumulated trash.
- Attempt to "smoke" a friend out of his room.
- Use of inflammable liquids as cleaning agents.
- Storage of inflammable liquids within a living area.
- Overloading electrical circuits.
- Extension cords which are suspended on nails or placed in a manner that causes wear of the

protective covering increases the possibility of short circuits.

- Leaving appliances plugged in and unattended.
- Poor housekeeping (accumulation of trash, newspapers, magazines, etc.).
- Operation of ventilating fan near drapes or curtains which may be drawn into the blades, stopping the machine, thus causing the motor to heat up and ignite the material.
- Drying clothing on heating devices.

Residents are also asked to remember these considerations:

- Do not tamper with fire alarms, fire extinguishers or other.
- Do not cover or disconnect the apartment smoke detectors.
- Do not hang items on sprinkler heads.
- Leaving food on the stove unattended is one of the main causes of fires.
- Keep breezeways and stairwells clear. Do not lock or store bicycles in stairwells.
- Smoke detectors should not be unhooked or covered as this is a fire code violation. Please make sure your smoke detectors are in working order. If not, contact Whitney Laboratory Facilities. Plans for future improvements in fire safety, if determined necessary by the institution.

UF SEPARATE CAMPUSES FACILITY UPGRADES

Ongoing upgrades to fire alarm systems including the installation/upgrade of fire sprinklers, heat detectors, smoke detectors, etc. are routinely budgeted for as part of the department Master Plan for facilities.

Fire Statistics and Review of Fire Safety

For the Gainesville, UF Health Jacksonville, and Separate Campuses



University of Florida Gainesville Campus Fire Statistics

Tigert Hall
Gainesville, FL 32611

The following table summarizes fire events on the University of Florida Gainesville Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

RESIDENTIAL FACILITY	Date	Time	Cause	Injuries	Death	Property Damage Value
2023						
Infinity Hall (978 SW 2nd Avenue)	01/30/2023	12:00PM	Machinery/Industrial/Laser Fire	0	0	\$100-999
Lakeside Bldg. 1185 (51 Lakeside Complex)	02/02/2023	08:59PM	Cooking Fire	0	0	\$1,000-9,999
East Hall 592 (528 Gale Lemerand Dr)	04/03/2023	12:49AM	Other	0	0	\$0-99
Diamond 302 (1402 Diamond Road)	05/08/2023	04:01PM	Cooking Fire	0	0	\$0-99
Beaty Towers East, 751 (11 Beaty Towers)	09/19/2023	02:54AM	Other/Unknown	0	0	\$100-999
2022						
Lakeside Bldg. 1 (51 Lakeside Complex)	01/16/2022	4:00PM	Cooking fire	0	0	\$0-99
Corry Village, Bldg. 279 (278 Corry Village)	05/06/2022	12:00AM	Cooking fire	1	0	\$1,000-9,999
Tanglewood Village (2903 SW 13th St)	09/28/2022	11:43AM	Cooking fire	0	0	\$0-99
2021						
Tanglewood Village, Bldg. 527 (2903 SW 13th St)	01/10/2021	9:00PM	Cooking-Stovetop grease fire	0	0	\$1,000-9,999
Thomas Hall Bldg. 17 (133 Fletcher Dr)	01/11/2021	12:20PM	Cooking fire	0	0	\$100-999
Maguire Village Bldg. 383 (377 Maguire Village)	05/28/2021	6:00PM	Cooking fire	0	0	\$100-999
Tanglewood Village, Bldg. 535 (2901 SW 13th St)	08/01/2021	12:30PM	Cooking-Stovetop grease fire	0	0	\$100-999
North Hall, Bldg. 50 (2063 Stadium Rd)	09/20/2021	3:39PM	HVAC-Electrical fire	0	0	\$100-999
Sledd Hall, Bldg. 16 (191 Fletcher Dr)	10/13/2021	7:58PM	HVAC-Electrical fire	0	0	\$100-999
North Hall, Bldg. 50 (2063 Stadium Rd)	11/16/2021	11:54PM	Cooking fire	0	0	\$100-999

TOTAL HOUSING

CAUSES OF FIRES	2021	2022	2023
Electrical	2	0	0
Cooking	5	3	2
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Mechanical/Industrial	0	0	1
Other	0	0	2
Total Fires Reported	7	3	5
INJURIES/DEATH			
Injuries	0	1	0
Deaths	0	0	0



Review of University of Florida Gainesville Fire Safety

Facility	Year Built	% Space Sprinkled	Fire Alarm	Total Sq. Footage	Sq. Ft. Sprin-	Ground Floor Sq. Ft.	Total Floors	Sprinkler Date	Number of Fire Drills in 2023
BROWARD & YULEE AREA									
Broward Hall 11 (680 Broward Dr)	1954	85.23%	Yes	159,100	135,600	9,680	6	2016-17	4
Rawlings Hall 553 (651 Newell Dr)	1958	0.00%	Yes	82,930	0	12,620	5	2024	4
Reid Hall 20 (1316 Museum Rd)	1939	100%	Yes	42,400	42,400	8,480	5	2005	4
Yulee Hall 39 (1358 Museum Rd)	1950	100%	Yes	43,350	43,350	8,670	5	2007	4
Mallory Hall 41 (1367 Inner Rd)	1950	100%	Yes	43,350	43,350	8,670	5	2006	4
Cypress Hall 86 (1310 Museum Rd)	2015	100%	Yes	83,500	83,500	16,420	5	2015	4
GREATER TOLBERT AREA									
Tolbert Hall 45 (2087 Stadium Rd)	1950	100%	Yes	54,300	54,300	8,320	6	2006	4
North Hall 50 (2063 Stadium Rd)	1950	100%	Yes	36,600	36,600	9,150	4	2005	4
Riker Hall 52 (2069 Stadium Rd)	1950	100%	Yes	43,440	43,440	3,730	6	2004	4
East Hall 592 (528 Gale Lemerand Dr)	1961	100%	Yes	44,230	44,230	8,846	4	2008	4
Weaver Hall 53 (562 Gale Lemerand Dr)	1950	100%	Yes	46,840	46,840	9,368	5	2012	4
KEYS COMPLEX • 44 KEYS RESIDENTIAL COLLEGE									
Keys Complex 1002	1989	100%	Yes	13,450	13,450	4,483	3	2007	4
Keys Complex 1003	1989	100%	Yes	13,450	13,450	4,483	3	2008	4
Keys Complex 1004	1989	100%	Yes	13,450	13,450	4,483	3	2009	4
Keys Complex 1005	1989	100%	Yes	13,450	13,450	4,483	3	2010	4
Keys Complex 1006	1989	100%	Yes	13,450	13,450	4,483	3	2011	4
Keys Complex 1007	1989	100%	Yes	13,450	13,450	4,483	3	2012	4
Keys Complex 1008	1989	100%	Yes	13,450	13,450	4,483	3	2014	4
Keys Complex 1009	1989	100%	Yes	13,450	13,450	4,483	3	2015	4
Keys Complex 1010	1989	100%	Yes	13,450	13,450	4,483	3	2016	4
SPRINGS COMPLEX • 45 SPRINGS RESIDENTIAL COMPLEX									
Springs Complex 1080	1995	100%	Yes	8,860	8,860	3,660	3	1995	4
Springs Complex 1081	1995	100%	Yes	18,550	18,550	4,638	4	1995	4
Springs Complex 1082	1995	100%	Yes	18,550	18,550	4,638	4	1995	4
Springs Complex 1083	1995	100%	Yes	18,550	18,550	4,638	4	1995	4
Springs Complex 1084	1995	100%	Yes	18,550	18,550	4,638	4	1995	4
Springs Complex 1085	1995	100%	Yes	18,550	18,550	4,638	4	1995	4
Springs Complex 1086	1995	100%	Yes	18,550	18,550	4,638	4	1995	4
LAKESIDE COMPLEX • 51 LAKESIDE COMPLEX									
Lakeside Complex 1181	2000	100%	Yes	30,255	30,255	10,085	3	2000	4
Lakeside Complex 1182	2000	100%	Yes	30,255	30,255	10,085	3	2000	4
Lakeside Complex 1183	2000	100%	Yes	30,255	30,255	10,085	3	2000	4

Review of University of Florida Gainesville Fire Safety continued

Facility	Year Built	% Space Sprinkled	Fire Alarm	Total Sq. Footage	Sq. Ft. Sprin-	Ground Floor Sq. Ft.	Total Floors	Sprinkler Date	Number of Fire Drills in 2023
LAKESIDE COMPLEX (CONT.)									
Lakeside Complex 1184	2000	100%	Yes	40,360	40,360	10,085	4	2000	4
Lakeside Complex 1185	2000	100%	Yes	40,360	40,360	10,085	4	2000	4
Lakeside Complex 1186	2000	100%	Yes	2,565	2,565	2,565	1	2002	4
BEATY & JENNINGS AREA									
Beaty Towers 750 (11 Beaty Towers)	1967	100%	Yes	82,810	82,810	5,915	14	1998	4
Beaty Towers 751 (11 Beaty Towers)	1967	100%	Yes	76,950	76,950	5,915	13	1999	4
Jennings Hall 593 & 595 (1509 Museum Rd)	1961	100%	Yes	108,920	108,920	18,820	5	2010	4
INFINITY HALL • 978 SW 2ND AVENUE									
Infinity Hall 3485	2015	100%	Yes	91,815	91,815	16,495	5	2015	4
GRAHAM AREA • 21 GRAHAM AREA									
Graham Hall 591	1961	0.00%	Yes	39,800	0	7,960	5	2019	4
Simpson Hall 590	1961	0.00%	Yes	38,930	0	7,786	5	2020	4
Trusler Hall 588	1961	0.00%	Yes	40,540	0	8,108	5	2021	4
HUME AREA • 19 HUME HONORS RESIDENTIAL COLLEGE									
Hume Halls 575	2002	100%	Yes	75,973	75,973	9,520	5	2002	4
Hume Halls 574	2002	100%	Yes	3,708	3,708	3,708	1	2002	4
Hume Halls 577	2002	100%	Yes	75,973	75,973	9,520	5	2002	4
MURPHREE AREA									
Murphree Hall 135 (110 Fletcher Dr)	1939	100%	Yes	97,450	97,450	21,612	4	1992	4
Thomas Hall 17 (133 Fletcher Dr)	1905	100%	Yes	35,920	35,920	11,973	3	1993	4
Sledd Hall 16 (191 Fletcher Dr)*	1929	33.00%	Yes	43,310	14,292	10,827	4	2022	4
Fletcher Hall 134 (72 Buckman Dr)*	1939	33.00%	Yes	50,500	16,665	12,625	4	2023	4
Buckman 15 (132 Buckman Dr)	1905	100%	Yes	29,580	29,580	9,860	3	1993	4
GRADUATE AND FAMILY HOUSING									
CORRY VILLAGE • 278 CORRY VILLAGE									
Corry Village 276	1958	100%	Yes	6,920	6,920	3,460	2	2013	0
Corry Village 277	1958	100%	Yes	10,910	10,910	5,455	2	2014	0
Corry Village 278	1958	100%	Yes	10,910	10,910	5,455	2	2015	0
Corry Village 279	1958	100%	Yes	10,910	10,910	5,455	2	1998	0
Corry Village 280	1958	100%	Yes	10,910	10,910	5,455	2	1998	0
Corry Village 281	1958	100%	Yes	10,910	10,910	5,455	2	2008	0
Corry Village 282	1958	100%	Yes	10,910	10,910	5,455	2	2014	0
Corry Village 283	1958	100%	Yes	10,910	10,910	5,455	2	2014	0
Corry Village 284	1958	100%	Yes	10,910	10,910	5,455	2	2015	0
Corry Village 285	1958	100%	Yes	10,910	10,910	5,455	2	2004	0
Corry Village 286	1958	100%	Yes	10,910	10,910	5,455	2	2014	0
Corry Village 288	1958	100%	Yes	18,410	18,410	9,205	2	2012	0
Corry Village 289	1958	100%	Yes	18,410	18,410	9,205	2	2011	0

Review of University of Florida Gainesville Fire Safety continued

Facility	Year Built	% Space Sprinkled	Fire Alarm	Total Sq. Footage	Sq. Ft. Sprin-	Ground Floor Sq. Ft.	Total Floors	Sprinkler Date	Number of Fire Drills in 2023
DIAMOND VILLAGE • 1402 DIAMOND ROAD									
Diamond Village 296	1965	100%	Yes	12,180	12,180	6,090	2	2002	0
Diamond Village 297	1965	100%	Yes	12,180	12,180	6,090	2	2003	0
Diamond Village 298	1965	100%	Yes	12,180	12,180	6,090	2	2003	0
Diamond Village 299	1965	100%	Yes	12,180	12,180	6,090	2	2004	0
Diamond Village 300	1965	100%	Yes	12,180	12,180	6,090	2	2004	0
Diamond Village 301	1965	100%	Yes	12,180	12,180	6,090	2	2004	0
Diamond Village 302	1965	100%	Yes	12,180	12,180	6,090	2	2001	0
Diamond Village 303	1965	100%	Yes	18,310	18,310	9,155	2	2003	0
Diamond Village 304	1965	100%	Yes	18,310	18,310	9,155	2	2004	0
Diamond Village 305	1965	100%	Yes	18,310	18,310	9,155	2	2003	0
Diamond Village 306	1965	100%	Yes	18,310	18,310	9,155	2	2002	0
MAGUIRE VILLAGE • 377 MAGUIRE VILLAGE									
Maguire Village 365	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 366	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 367	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 368	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 369	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 370	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 371	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 372	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 373	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 374	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 375	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 376	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 378	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 379	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 380	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 381	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 382	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 383	1971	0.00%	No	3,690	0	1,845	2	N/A	0
Maguire Village 384	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 385	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 386	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 387	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 388	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 389	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 390	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 391	1971	0.00%	No	7,330	0	3,665	2	N/A	0

Review of University of Florida Gainesville Fire Safety continued

Facility	Year Built	% Space Sprinkled	Fire Alarm	Total Sq. Footage	Sq. Ft. Sprin-	Ground Floor Sq. Ft.	Total Floors	Sprinkler Date	Number of Fire Drills in 2023
MAGUIRE VILLAGE (CONT.)									
Maguire Village 392	1971	0.00%	No	7,330	0	3,665	2	N/A	0
Maguire Village 393	1971	0.00%	No	7,330	0	3,665	2	N/A	0
TANGLEWOOD VILLAGE • 2901 SW 13TH STREET									
Tanglewood Village 527	1973	0.00%	Yes	12,530	0	6,265	2	2025	0
Tanglewood Village 528	1973	0.00%	Yes	7,320	0	3,660	2	2025	0
Tanglewood Village 529	1973	0.00%	Yes	7,320	0	3,660	2	2025	0
Tanglewood Village 530	1973	0.00%	Yes	7,320	0	3,660	2	2025	0
Tanglewood Village 532	1973	0.00%	Yes	14,150	0	7,075	2	2026	0
Tanglewood Village 533	1973	0.00%	Yes	17,690	0	8,845	2	2026	0
Tanglewood Village 535	1973	0.00%	Yes	10,720	0	5,360	2	2026	0
Tanglewood Village 536	1973	0.00%	Yes	9,840	0	4,920	2	2026	0
Tanglewood Village 538	1973	0.00%	Yes	92,400	0	46,200	2	2026	0
Tanglewood Village 539	1973	0.00%	Yes	9,800	0	4,900	2	2026	0
UNIVERSITY VILLAGE SOUTH • 1499 BLUE CIRCLE									
University Village South 318	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 319	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 320	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 321	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 322	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 323	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 324	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 325	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 326	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 327	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 328	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 329	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 330	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 331	1972	0.00%	No	7,330	0	3,665	2	N/A	0
University Village South 333	1972	0.00%	No	7,330	0	3,665	2	N/A	0
CONTINUUM • 425 W UNIVERSITY AVENUE									
Continuum Building 2	2011	100%	Yes	89,904	89,904	21,713	4	2011	0
Continuum Building 3	2011	100%	Yes	110,568	110,568	23,094	5	2011	0
Continuum Building 4	2011	100%	Yes	126,555	126,555	26,066	5	2011	0
HONORS VILLAGE • 1512 MUSEUM ROAD¹									
Honors Village Building 1	2023	100%	Yes	80,562	80,562	20,140 (approx)	4	2023	1
Honors Village Building 2	2024	100%	Yes	92,760	92,760	18,552 (approx)	5	2024	0
Honors Village Building 3	2023	100%	Yes	103,935	103,935	20,787 (approx)	5	2023	1
Honors Village Building 4	2024	100%	Yes	114,514	114,514	22,902 (approx)	5	2024	0

¹ Honors Village residential housing facility - Buildings 1 & 3 - came online Fall 2023. Buildings 2 & 4 came online Fall 2024.

Review of University of Florida Gainesville Fire Safety continued

Facility	Year Built	% Space Sprinkled	Fire Alarm	Total Sq. Footage	Sq. Ft. Sprin-	Ground Floor Sq. Ft.	Total Floors	Sprinkler Date	Number of Fire Drills in 2023
IFAS RESIDENCES**									
Beef Teaching Unit 0891 (3721 SW 23rd St)	2017	100%	Yes	1623	1623	1623	1	2017	1
Meats Lab 0867 (2122 Shealy Dr)	2012	100%	Yes	924	924	924	1	2012	1
Swine Unit (2359 SW 23rd Terr)	1971	0.00%	No	126	0	126	1	N/A	1
Swine Barn (2345 SW 23rd Terr)	1967	0.00%	No	252	0	252	1	N/A	1
Env. Hort. Turfgrass (1388 Orchard Dr)	1993	0.00%	No	687	0	687	1	N/A	1
GH Complex (2401 Memorial Rd)	1988	0.00%	No	821	0	821	1	N/A	1
Santa Fe Beef Ranch (1402 NW 294th Ave,	2012	0.00%	No	672	0	672	1	N/A	1

OTHER RESIDENCES

Stadium House¹

1642 W University Ave, Gainesville, FL 32603

2022	N/A	N/A	142,201	N/A	N/A	6	2022	N/A
------	-----	-----	---------	-----	-----	---	------	-----

¹ This off campus apartment is not owned or controlled by the University of Florida. However, the University Athletic Association has placed a number of UF student athletes in this apartment starting Fall 2022. As such, this apartment is classified as a residential housing facility for the duration that UF students are housed at this location.

* Bedrooms are not sprinkled; only corridors are sprinkled.

** IFAS Residences are maintained by the University of Florida Institute of Food and Agricultural Sciences; these locations are not maintained by UF Housing & Residence Life.

Sprinkler dates indicated with N/A are scheduled to be phased out of the Housing inventory by 2023.

Fire Alarm Systems refers to fire alarm systems that are monitored by UFPD, smoke detection, fire extinguisher devices and evacuation plan & placards posted on each student room door. All Housing and Residence Life facilities are equipped with fire extinguishers in compliance with currently adopted NFPA 10 coverage requirements. All extinguishers are inspected monthly by University of Florida Fire Equipment Services and all required testing is completed and performed as required by NFPA 10.



Review of University of Florida Gainesville Fire Safety

COVID-19 Temporary Housing Spaces used in calendar year 2021

In 2021, in response to the novel coronavirus COVID-19, temporary housing spaces at local hotels in the Gainesville, FL area were provided for students who were quarantined due to an exposure or positive COVID-19 test. Contracts between the University of Florida and these hotels were established to reserve space for students who would need to be relocated for quarantine or isolation purposes, upon need. These contracts were signed in August 2020, in preparation for the Fall 2020 Academic semester and were available as needed.

Starting in reporting year 2020, the U.S. Department of Education has advised per Appendix C "2021 Clery Act geography - COVID-19 information" of the 2021 User's Guide for CSS Web-based Data Collection that if institutions have contracted hotels or other spaces for quarantine due to COVID-19 that this space should be considered both on-campus and an on-campus student housing facility for the period that students were assigned to live there for quarantine. Additionally, if the institution repurposed a nonresidential campus facility for the purpose of quarantine, this space should be considered on-campus student housing facility during the time that students were assigned to live there as a part of quarantine. As the below hotels were used as temporary housing spaces in calendar year 2021, these spaces will be included in the Annual Fire Safety Report and reported as student housing facilities* for the period that students were assigned to live there for quarantine.

In calendar years 2022 and 2023, there were no temporary housing spaces at local hotels in Gainesville, FL provided for students who were quarantined due to an exposure or positive COVID-19 test.

Facility	Year Built	% Space Sprinkled	Fire Alarm	Total Sq. Footage	Sq. Ft. Sprinkled	Ground Floor Sq. Ft.	Total Floors	Sprinkler Date	Fire Sprinkler System	System Permit Date	Number of Fire Drills
2021											
QUALITY INN UNIVERSITY • 2435 SW 13TH ST. GAINESVILLE, FL 32608+											
Duration of housing: 01/26-02/11	1988	N/A	N/A	30,257	N/A	N/A	2	N/A	N/A	N/A	N/A
DAYS INN • 920 NW 69TH TERR. GAINESVILLE, FL 32605											
Duration of housing: 01/27-02/11	1989	N/A	N/A	130,192	N/A	N/A	4	N/A	N/A	N/A	N/A

* 34 CFR 668.49(b)

**The Staybridge Suites and Holiday Inn Express occupy conjoined physical space, but operate as two separate hotels

+Fire safety information for these hotels was obtained through publicly accessible information

FIRE SAFETY POLICIES

While these hotels were used as temporary housing spaces, the University of Florida did not have control over the Staybridge Suites, Holiday Inn Express, and the Quality Inn, therefore fire safety related information for each of these spaces was dependent on and managed by the individual hotel on-site management. Policies regarding the use of portable electrical appliances, smoking and open flames, and procedures for evacuation in case of a fire are provided to each guest upon arrival and within in the room itself, in accordance with H.R. 94 and F.S.S. 509.215. A person should report a fire by calling 9-1-1.

As the Reitz Union Hotel is a nonresidential campus facility managed by UF, this space will be considered an on-campus student housing facility during the time that students were assigned to live there as a part of quarantine. Policies regarding the use of portable electrical appliances, smoking and open flames, and procedures for evacuation in case of a fire are provided to the guest upon arrival and within in the room itself, in accordance with H.R. 94 and F.S.S. 509.215. A person should report a fire by calling 9-1-1 or a Building Supervisor at (352)260-3545. There are no plans for future improvements to fire safety for the Reitz Union Hotel.

CAUSES OF FIRES	2021
Electrical	0
Cooking	0
Smoking	0
Candles	0
Arson	0
Other	0
Total Fires Reported	0
INJURIES/DEATH	
Injuries	0
Deaths	0

UF Health Jacksonville

Fire Statistics

648 W 11th St.
Jacksonville, FL 32209

The following table summarizes fire events on the UF Health Jacksonville Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of UF Health Jacksonville Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
UDC Dormitory Building*	1953	-	Yes	13,558	Yes	3	1

*The UDC Dormitory Building is owned by the City of Jacksonville and leased by UF Health Jacksonville.



Citrus Research and Education Center Fire Statistics

700 Experiment Station Rd.
Lake Alfred, FL 33850-229

The following table summarizes fire events on the Citrus Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Citrus Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Graduate Residence - 7172	2017	100	Yes	2,916	Yes	1	1



Everglades Research and Education Center Fire Statistics


3200 E Palm Beach Rd.
Belle Glade, FL 33430

The following table summarizes fire events on the Everglades Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Everglades Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Residence - 7410	1930	0%	No	1060	Yes	1	1
Dormitory - 7411	1994	0%	No	3180	Yes	1	1
Residence - 7412	1930	0%	No	1200	Yes	1	1
Multi-Purpose Facility - 7493	2009	100%	Yes	1884	Yes	1	1



Florida Medical Entomology Laboratory Fire Statistics

200 SE 9th St.
Vero Beach, FL 32962

The following table summarizes fire events on the Florida Medical Entomology Laboratory for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Florida Medical Entomology Laboratory Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Office/Lab/Bunker Building	2003	0%	No	2,300	Yes	1	1



Fort Lauderdale Research and Education Center Fire Statistics

3205 College Ave.
Davie, FL 33314

The following table summarizes fire events on the Fort Lauderdale Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Fort Lauderdale Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Graduate Residence - 5051	2005	100%	Yes	2,426	Yes	1	1
Residence - 5062	2007	0%	No	924	Yes	1	1
Graduate Residence - 5078	2010	100%	Yes	2,640	Yes	1	1



Gulf Coast Research and Education Center Fire Statistics

14625 CR 672
Wimauma, FL 33598

The following table summarizes fire events on the Gulf Coast Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

RESIDENTIAL FACILITY

Date Time Cause Injuries Death Property Damage Value

2021

Graduate Residence 5236	03/18/2021	5:23PM	Electrical	0	0	\$50,000-99,999
-------------------------	------------	--------	------------	---	---	-----------------

TOTAL HOUSING

CAUSES OF FIRES	2021	2022	2023
Electrical	1	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	1	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$50,000-99,999	\$0	\$0

Review of Gulf Coast Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Farm Worker Residence 5205	2006	0%	No	812	Yes	1	1
Multi-Purpose Facility - 5206	2009	100%	Yes	2,542	Yes	1	1
Graduate Residence - 5209	2004	100%	Yes	2,649	Yes	1	1
Residence - 5222	2015	100%	Yes	2,300	Yes	1	1
Graduate Residence - 5236	2019	100%	Yes	2,800	Yes	1	1



IFAS Equine Science Center Fire Statistics

2655 NW 100th St.
Ocala, FL 34475

The following table summarizes fire events on the IFAS Equine Sciences Center Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of IFAS Equine Science Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Horse Research Unit 7201	2015	0%	Yes	1210	yes	1	1
Horse Research Unit 7220	2000	0%	No	1248	yes	1	1



IFAS Horse Teaching Unit Fire Statistics

1934 SW 63rd Ave.
Gainesville, FL 32608

The following table summarizes fire events on the IFAS Horse Teaching Unit for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of IFAS Horse Teaching Unit Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Horse Teaching Unit 1352	2000	0%	No	1456	yes	1	1
Horse Teaching Unit 1986	1986	0%	No	1866	yes	1	1



Indian River Research and Education Center Fire Statistics

2199 S Rock Rd.
Ft. Pierce, FL 34945

The following table summarizes fire events on the Indian River Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Indian River Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Graduate Residence - 7357	2004	100%	Yes	2,485	Yes	1	1
Residence - 7310	1956	0%	No	1,330	Yes	1	1



Mid Florida Research and Education Center Fire Statistics

2725 Binion Rd.
Apopka, FL 32703

The following table summarizes fire events on the Mid Florida Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Mid Florida Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Multi-Purpose Facility 4004	2011	100%	Yes	3,354	Yes	1	1



North Florida Research and Education Center (Marianna) Fire Statistics

3925 Hwy 71
Marianna, FL 32446

The following table summarizes fire events on the North Florida Research and Education Center (Marianna) for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of North Florida Research and Education Center (Marianna) Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Multi-Purpose Facility - 8032	2012	100%	Yes	2,408	Yes	1	1



North Florida Research and Education Center (Quincy) Fire Statistics

155 Research Rd.
Quincy, FL 32351

The following table summarizes fire events on the North Florida Research and Education Center (Quincy) for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of North Florida Research and Education Center (Quincy) Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Graduate Residence - 7921	2001	100%	Yes	1,944	Yes	1	1



Preservation Institute Nantucket Fire Statistics

11 Centre St
Nantucket, MA 02554

The following table summarizes fire events on the Preservation Institute Nantucket Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Preservation Institute Nantucket Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Dormitory	1989	0%	yes	2880	yes	1	1
Cottage 1	2000	100%	yes	530	yes	1	1
Cottage 2	2000	100%	yes	520	yes	1	1
Cottage 3	2018	100%	yes	520	yes	2	1



Range Cattle Research and Education Center Fire Statistics

3401 Experimental Station
Ona, FL 33865-9706

The following table summarizes fire events on the Range Cattle Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Range Cattle Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Residence - 8109	1942	0%	No	710	Yes	1	1
Multi-Purpose Facility - 8154	2009	100%	Yes	2,284	Yes	1	1



Southwest Florida Research and Education Center Fire Statistics

2686 N Hwy 29
Immokalee, FL 34142-9515

The following table summarizes fire events on the Southwest Florida Research and Education Center for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Southwest Florida Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Multi-Purpose Facility	2008	100%	Yes	1,982	Yes	1	1
Residence - 7705	1999	0%	No	960	Yes	1	1
Residence - 7706	1961	0%	No	1,590	Yes	1	1



Tropical Aquaculture Laboratory Fire Statistics

1408 SE 24th St.
Ruskin, FL 33570

The following table summarizes fire events on the Tropical Aquaculture Laboratory Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Tropical Aquaculture Laboratory Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Graduateesidence - 9407	2005	0%	No	896	Yes	1	1



Tropical Research and Education Center Fire Statistics

18905 SW 280 St.
Homestead, FL 33031-3314

The following table summarizes fire events on the Tropical Research and Education Center Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Tropical Research and Education Center Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Residence - 8212	1992	0%	No	1,875	Yes	1	1
Graduate Residence - 8268	2008	100%	Yes	1,884	Yes	1	1
Graduate Residence - 8269	2008	100%	Yes	1,884	Yes	1	1
Graduate Residence - 8270	2008	100%	Yes	1,884	Yes	1	1



Vicenza Institute of Architecture

Fire Statistics

Contra S.S. Apostoli, 51
36100 Vicenza VI , Italy

The following table summarizes fire events on the Vicenza Institute of Architecture Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Vicenza Institute of Architecture Fire Safety

FACILITY	Year Built	% Space Sprinkled ¹	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Apartment #3 (Piazzetta Ss. Apostoli 1 - int. 5)	18th century	0%	no	1600	no	1	2
Apartment #4 Int. 1 (Contra Ss. Apostoli 51 - Scala B)	18th century	0%	no	540	no	1	2
Apartment #4 Int. 2 (Contra Ss. Apostoli 51 - Scala B)	18th century	0%	no	900	no	1	2
Apartment #5 (Contra Ss. Apostoli 51 - Scala A - int. 2)	19th century	0%	no	900	no	1	2
Apartment #6 (Contra Ss. Apostoli 6 - int. 1)	19th century	0%	no	860	no	1	2
Apartment #7 (Contra Ss. Apostoli 51 - Scala A - int. 8) ²	19th century	0%	no	860	no	1	2

¹ Please note that Italian fire code requires special permissions for the use of sprinklers, and in residential buildings they most often cannot be installed.

² This apartment was rented in 2023, was not in use/rented in prior years.



West Florida Research and Education Center (Jay)

Fire Statistics

4253 Experiment Dr., Hwy 182

Jay, FL 32565

The following table summarizes fire events on the West Florida Research and Education Center (Jay) Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of West Florida Research and Education Center (Jay) Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Graduate Residence - 8424	1948	100%	Yes	1,179	Yes	1	1



Whitney Laboratory for Marine Bioscience Fire Statistics

9505 N Ocean Shore Blvd.
St. Augustine, FL 32080

The following table summarizes fire events on the Whitney Laboratory Campus for three years. Causes of each fire, damages caused by each fire, general location of each fire, injuries and death resulting from each fire are included in the summary report.

CAUSES OF FIRES	TOTAL HOUSING		
	2021	2022	2023
Electrical	0	0	0
Cooking	0	0	0
Smoking	0	0	0
Candles	0	0	0
Arson	0	0	0
Other	0	0	0
Total Fires Reported	0	0	0
Injuries	0	0	0
Deaths	0	0	0
Property Damage	\$0	\$0	\$0

Review of Whitney Laboratory for Marine Bioscience Fire Safety

FACILITY	Year Built	% Space Sprinkled	Fire Alarm Systems	Total Sq. Footage	Extinguishers Provided	Total Floors	Number of Fire Drills in 2023
Dorm Bldg. 1013	1989	0%	yes	9935	yes	1	1
Dorm Bldg. 2092	2000	100%	yes	1152	yes	1	1
Dorm Bldg. 2093	2000	100%	yes	1152	yes	1	1
Building 2094	2018	100%	yes	1295	yes	2	1
Building 2095	2018	100%	yes	1295	yes	2	1
Building 2096	2018	100%	yes	1295	yes	2	1
Building 2097	2018	100%	yes	1295	yes	2	1
Building 2098	2018	100%	yes	1295	yes	2	1
Building 2099	2018	100%	yes	1295	yes	2	1





UF

Compliance and Ethics

Clery Compliance

UNIVERSITY of FLORIDA

Clery Act Compliance officer
720 SW 2nd Ave. Suite 106
Gainesville, FL 32601

clery@ufl.edu
<https://clery.compliance.ufl.edu/>